398th Bombardment Group Formation Chart Mission 82: 13 September 1944 - Target: Lutzkendorf, Germany **Over Target**

Lead Group 1st "B" CBW [602]

Hunter Dunlap 8031-K PFF 13 September 1944

Connoly Templeman * 2507-F

Allen

8010-E PFF

Boehme 7180-S

Hancock Erler 7183-J 7094-M

8164-H

Doerr Payne 7387-H **

Rudow 7374-X

Leukhardt Hall 2506-L 7150-K

* Load List and Interrogation Report show Captain Templeman as CA.

** Planned and After Assembly show Payne in A/C 2593-C, but pencil entry on Planned Formation Chart indicates A/C 7387-H and is confirmed in Flight Log.

*** A/C 42-102390 N8-X Radnedge - Not a pathfinder. Was a sortie. Left formation over enemy territory and returned to home base due to broken exhaust collector ring at No. 1 cylinder on No. 4 engine. a target of opportunity at 5027N - 0634E. Since there is no Over Target Formation Chart it is unknown who moved to replace Radnedge as lead. Probably it is 7094-M Erler.

High Group 1st "B" [603]

Scott Durtschi 8044-X PFF

Meyran Khourie 2562-G

8091-L

Newman * 7138-T

Ullom 7977-R

Hastings 7078-U

Wisner Howden 6083-V 8075-A Hyndman 8086-C

Rehme 2536-C

Buzza Lee 8463-X 2519-A

* A/C 42-107053 N7-M Sleaman — Not a pathfinder. Not a sortie. Left formation because pilot noticed a small [amount] of fuel in the cabin. A/C returned to home base. Newman's Interrogation Report indicates he moved up to Sleaman's spot as Lead of Low Squadron High Group. Hyndman may have moved over to take Newman's original spot as #2.

Continued Next Page

398th Bombardment Group Formation Chart Mission 82: 13 September 1944 - Target: Lutzkendorf, Germany **Over Target**

Low Group "B" 1st CBW [601]

Arlin * Scofield 7889-B

Sitler Wierney 2596-M 8121-Q

Marias 8129-A

Conrow Rogers 2607-F 7338-C

8172-P Curtis 7190-L

Campbell

Cucco 8064-H

DeLancey Morrison 7846-T 7401-T

* Load List, Interrogation Report and Flight Log show Captain Arlin as CA, but his diary indicates Captain Schofield was.

** A/C 42-107203 30-Z Taylor - Not a pathfinder. Was a sortie. Left formation over enemy territory and returned to home base because pilot reported he could get no boost from No. 1 supercharger. Attacked a target of opportunity at 5018N - 0728E. It is likely Campbell and Curtis maintained their positions in the element.

Spare: A/C E-7387-H Area D-6 [Appears to have been used by Payne instead of 2593-C]

Lead Regular Briefing 0400 0445 Stations 0600 0600 Engines 0625 0635 Taxi 0635 0645 Take-Off 0655 0705

Note: The 398^{th} files did not contain an Over Target Formation Chart. Three aircraft left the formation After Assembly. These are noted above. Some information is provided as possibly who might have filled their positions.

- Planned Formation Chart (PDF 1757, 1850)
- After Assembly Chart (PDF 1711)
- Over Target Chart (Not Found)
- Flight Log (PDF 1715, 1744)
- Operations Officer's Report (PDF 1705-0707)

398th History CD File: B0483d.pdf

PDF Page: Not Found

Numbered Page: Not Found

Transcribed By: Dave Jordan, March 2009